



GARY R. HERBERT
Governor

SPENCER J. COX
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report

Minerals Regulatory Program

December 16, 2013

Reviewed:

Mine Name: Green Peak Quarry	Permit Number: M/003/0060
Operator Name: I&P Inveystments	Inspection Date: June 4, 2013
Inspector(s): Lynn Kunzler and Steve Schneider	Time: 2:30 pm
Other Participants: None	Mine Status: inactive

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts,	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:
Routine Inspection.

Inspection Summary:

The annual permit fee for the last two years has not been paid, the operator now owes \$1000 to bring the fees current. The Division currently holds a reclamation surety (LOC) of \$117,000 which is due for escalation in May of 2015.

The mill area along the Immigrant Pass Road has yet to be reclaimed. The NOI had made a commitment to reclaim this area when the new dump site/work area was developed near the quarry. This reclamation work needs to be done ASAP. The site has now been inactive for 9 years. The operator needs to consider reclaiming the site this year, or will need to request a hearing before the Board of Oil Gas and Mining to request an extension to continue the inactive status beyond ten years (otherwise enforcement action may be taken).

While the site appeared to be stable, there is considerable amount of garbage located at the new dump/ work area. There is also what may now be considered an abandoned haul truck at this site (repairs on this truck appear to have been started several years ago and were never completed – the rear hub has not been re-assembled).

Currently the public has free access to this site. The operator should consider at least placing signs at the access road warning the public of the mine and to restrict access to authorized personnel only.

Photos were taken to document site conditions

Inspection Date: June 4, 2013


Page 2 of 2

M/003/0060

Conclusions and Recommendations:

The garbage needs to be cleaned up or potential enforcement action may happen. The repairs to the haul truck need to be completed or the truck should be removed from the site. If the site is not active next year, the reclamation needs to be done before the end of the year.

Inspector's Signature

A handwritten signature in black ink, appearing to be 'M. Nelson', written over a horizontal line.

cc: Michael Pauletto, Operator

Michael Nelson, BLM, (mnelson@blm.gov)

O:\M003-BoxElder\M0030060-GreenPeak\inspections\Insp-06042013.doc